



Helping Restore Lives

Lawton Construction & Restoration Inc
PO BOX 1966
Lincoln, CA 95648
8669905150
ar@lawtoncr.com
www.lawtoncr.com

BILL TO

LIN-24-854-TMP;60
60 Creeks Edge Way
SACRAMENTO, CA 95814 USA

INVOICE 101137

DATE 01/21/2025 **TERMS** Due on receipt

DUE DATE 01/21/2025

JOB ADDRESS

60 & 64 Creeks Edge Way

DATE	DESCRIPTION	QTY	RATE	AMOUNT
	Income - Emergency Services	1	2,250.00	2,250.00
	Emergency Services roof repairs for 60 & 64 Creeks Edge Way			

3% fee for all credit card payments will apply.
Please contact Lawton Construction & Restoration Inc to pay via credit card.

Thank you for your business.

CA License #891067

NV License #0080163

PAYMENT 2,250.00

TOTAL DUE \$0.00

Ways to pay

BANK

[View and pay](#)

3% fee for all credit card payments will apply.
Please contact Lawton Construction & Restoration Inc to pay via credit card.



Helping Restore Lives

Lawton Construction & Restoration Inc
PO BOX 1966
Lincoln, CA 95648
8669905150
ar@lawtoncr.com
www.lawtoncr.com

BILL TO

Wildwood Homeowner's
Association
LIN-25-166-MLD;4103
4088 Savannah Ln
Sacramento, CA 95823 USA

INVOICE 101413-7415

DATE 03/18/2025 **TERMS** Due on receipt

DUE DATE 03/18/2025

JOB ADDRESS

4103 Weymouth Ln

DATE	DESCRIPTION	QTY	RATE	AMOUNT
	Income - Abatement			
	Abatement- 4103 Weymouth Ln	1	2,940.00	2,940.00

3% fee for all credit card payments will apply.
Please contact Lawton Construction & Restoration Inc to pay via credit card.

Thank you for your business.

CA License #891067

NV License #0080163

PAYMENT 2,940.00

TOTAL DUE \$0.00

Ways to pay

BANK

[View and pay](#)

3% fee for all credit card payments will apply.
Please contact Lawton Construction & Restoration Inc to pay via credit card.



Helping Restore Lives

Lawton Construction & Restoration Inc
PO BOX 1966
Lincoln, CA 95648
8669905150
ar@lawtoncr.com
www.lawtoncr.com

BILL TO

Wildwood Homeowner's
Association

INVOICE 105412

DATE 10/03/2025 **TERMS** Due on receipt

DUE DATE 10/03/2025

JOB ADDRESS

4075 Savannah Ln

DATE	DESCRIPTION	QTY	RATE	AMOUNT
	Income - Emergency Services	1	1,433.19	1,433.19

3% fee for all credit card payments will apply.
Please contact Lawton Construction & Restoration Inc to pay via credit card.

Thank you for your business.

CA License #891067

NV License #0080163

Please mail all payments to:

PO BOX 1966

Lincoln, CA 95648

PAYMENT

1,433.19

TOTAL DUE

\$0.00

Ways to pay

BANK

[View and pay](#)

3% fee for all credit card payments will apply.
Please contact Lawton Construction & Restoration Inc to pay via credit card.



Lawton Construction & Restoration

PO Box 1966
Lincoln CA 95648
Tax id: 20-5680762

4149_BROOKFIELD_TMP

4149_BROOKFIELD_TMP

CAT	SEL	ACT DESCRIPTION				
	CALC	QTY	REMOVE	REPLACE	TAX	TOTAL
1. SCF	RNTHLD	+ Fall protection harness and lanyard (per day)				
	1	1.00 DA	0.00+	8.00 =	0.00	8.00
2. RFG	HIGH	+ Additional charge for high roof (2 stories or greater)				
	3	3.00 SQ	0.00+	41.31 =	0.00	123.93
3. TMP	TARPS	+ Tarp - poly - w/sandbags - per sq ft (lab & mat)				
	300	300.00 SF	0.00+	3.10 =	14.96	944.96
Total: 4149_BROOKFIELD_TMP					14.96	1,076.89
Line Item Totals: 4149_BROOKFIELD_TMP					14.96	1,076.89



Lawton Construction & Restoration

PO Box 1966
Lincoln CA 95648
Tax id: 20-5680762

Client: 4096 WEYMOUTH LN
Property: 4096 WEYMOUTH LN
SACRAMENTO , CA 95823

Operator: TRAVI

Estimator: Travis Gabourie

Business: (530) 308-0728

Type of Estimate:

Date Entered: 10/2/2025

Date Assigned:

Price List: CASA8X_OCT25

Labor Efficiency: Restoration/Service/Remodel

Estimate: 4096_WEYMOUTH_LN_TMP

Emergency Roof Estimate



Lawton Construction & Restoration

PO Box 1966
Lincoln CA 95648
Tax id: 20-5680762

4096_WEYMOUTH_LN_TMP

4096_WEYMOUTH_LN_TMP

CAT	SEL	ACT DESCRIPTION		REMOVE	REPLACE	TAX	TOTAL
	CALC	QTY					
1. SCF	RNTHLD	+ Fall protection harness and lanyard (per day)					
	1	1.00 DA		0.00+	8.00 =	0.00	8.00
2. RFG	HIGH	+ Additional charge for high roof (2 stories or greater)					
	1	1.00 SQ		0.00+	41.31 =	0.00	41.31
3. TMP	TARPS	+ Tarp - poly - w/sandbags - per sq ft (lab & mat)					
	100	100.00 SF		0.00+	3.10 =	4.99	314.99
Total: 4096_WEYMOUTH_LN_TMP						4.99	364.30
Line Item Totals: 4096_WEYMOUTH_LN_TMP						4.99	364.30



Lawton Construction & Restoration

PO Box 1966
Lincoln CA 95648
Tax id: 20-5680762

Summary

Line Item Total	359.31
Material Sales Tax	4.99
Replacement Cost Value	\$364.30
Net Claim	\$364.30

Travis Gabourie



Lawton Construction & Restoration

PO Box 1966
Lincoln CA 95648
Tax id: 20-5680762

Recap of Taxes

	Material Sales Tax (8.75%)	Storage Rental Tax (8.75%)
Line Items	4.99	0.00
Total	4.99	0.00



Lawton Construction & Restoration

PO Box 1966
Lincoln CA 95648
Tax id: 20-5680762

Recap by Room

Estimate: 4096_WEYMOUTH_LN_TMP	359.31	100.00%
Subtotal of Areas	359.31	100.00%
Total	359.31	100.00%



Lawton Construction & Restoration

PO Box 1966
Lincoln CA 95648
Tax id: 20-5680762

Recap by Category

Items	Total	%
ROOFING	41.31	11.34%
SCAFFOLDING	8.00	2.20%
TEMPORARY REPAIRS	310.00	85.09%
Subtotal	359.31	98.63%
Material Sales Tax	4.99	1.37%
Total	364.30	100.00%



Loss Type:

Date Of Loss:

Loss Category:Residential

Customer Name:Wildwood Homeowner's Association

E-mail Address:

Job Address:4096 WEYMOUTH LN
SACRAMENTO, CA, 95823

Main Contact Number:1-916-392-3613

Billing Address:4088 Savannah Ln
Sacramento, CA, 95823

Job Number:LIN-25-700-TMP Album:Ricardo_pics



File Name:Ricardo pics_0001.jpg

Description:Front elevation

HiRes Image URL:[Click Me](#)

Job Number:LIN-25-700-TMP Album:Ricardo_pics




File Name:Ricardo pics_0002.jpg

Description:Overview pic of damage in roof

HiRes Image URL:[Click Me](#)

Job Number:LIN-25-700-TMP Album:Ricardo pics



File Name:Ricardo pics_0003.jpg

Description:Overview picture of damage in roof

HiRes Image URL:[Click Me](#)

Job Number:LIN-25-700-TMP Album:Ricardo pics



File Name:Ricardo pics_0005.jpg

Description:Roof tarp

HiRes Image URL:[Click Me](#)

Job Number:LIN-25-700-TMP Album:Ricardo pics



File Name:Ricardo pics_0006.jpg

Description:Roof tarp to prevent water damage

HiRes Image URL:[Click Me](#)

Job Number:LIN-25-700-TMP Album:Ricardo pics



File Name:Ricardo pics_0004.jpg

Description:Roof tarp to prevent water go inside the house

HiRes Image URL:[Click Me](#)



Lawton Construction & Restoration

PO Box 1966
Lincoln CA 95648
Tax id: 20-5680762

Client: 4050 WEYMOUTH LN
Property: 4050 WEYMOUTH LN
SACRAMENTO , CA 95823

Operator: TRAVI

Estimator: Travis Gabourie

Business: (530) 308-0728

Type of Estimate:

Date Entered: 10/2/2025

Date Assigned:

Price List: CASA8X_OCT25

Labor Efficiency: Restoration/Service/Remodel

Estimate: 4050_WEYMOUTH_LN_T-1

Emergency Roof Estimate



Lawton Construction & Restoration

PO Box 1966
Lincoln CA 95648
Tax id: 20-5680762

4050_WEYMOUTH_LN_T-1

4050_WEYMOUTH_LN_T-1

CAT	SEL	ACT DESCRIPTION		REMOVE	REPLACE	TAX	TOTAL
	CALC	QTY					
1. SCF	RNTHLD	+ Fall protection harness and lanyard (per day)					
	1	1.00 DA		0.00+	8.00 =	0.00	8.00
2. RFG	HIGH	+ Additional charge for high roof (2 stories or greater)					
	4	4.00 SQ		0.00+	41.31 =	0.00	165.24
3. TMP	TARPS	+ Tarp - poly - w/sandbags - per sq ft (lab & mat)					
	400	400.00 SF		0.00+	3.10 =	19.95	1,259.95
Total: 4050_WEYMOUTH_LN_T-1						19.95	1,433.19
Line Item Totals: 4050_WEYMOUTH_LN_T-1						19.95	1,433.19



Lawton Construction & Restoration

PO Box 1966
Lincoln CA 95648
Tax id: 20-5680762

Summary

Line Item Total	1,413.24
Material Sales Tax	19.95
Replacement Cost Value	\$1,433.19
Net Claim	\$1,433.19

Travis Gabourie



Lawton Construction & Restoration

PO Box 1966
Lincoln CA 95648
Tax id: 20-5680762

Recap of Taxes

	Material Sales Tax (8.75%)	Storage Rental Tax (8.75%)
Line Items	19.95	0.00
Total	19.95	0.00



Lawton Construction & Restoration

PO Box 1966
Lincoln CA 95648
Tax id: 20-5680762

Recap by Room

Estimate: 4050_WEYMOUTH_LN_T-1	1,413.24	100.00%
Subtotal of Areas	1,413.24	100.00%
Total	1,413.24	100.00%



Lawton Construction & Restoration

PO Box 1966
Lincoln CA 95648
Tax id: 20-5680762

Recap by Category

Items	Total	%
ROOFING	165.24	11.53%
SCAFFOLDING	8.00	0.56%
TEMPORARY REPAIRS	1,240.00	86.52%
Subtotal	1,413.24	98.61%
Material Sales Tax	19.95	1.39%
Total	1,433.19	100.00%



Loss Type:

Date Of Loss:

Loss Category:Residential

Customer Name:Wildwood Homeowner's Association

E-mail Address:

Job Address:4050 WEYMOUTH LN
SACRAMENTO, CA, 95823

Main Contact Number:1-916-392-3613

Billing Address:4088 Savannah Ln
Sacramento, CA, 95823

Job Number:LIN-25-701-TMP Album:Ricardo pics



File Name:Ricardo pics_0002.jpg

Description:Front elevation

HiRes Image URL:[Click Me](#)

Job Number:LIN-25-701-TMP Album:Ricardo pics



File Name:Ricardo pics_0015.jpg
Description:Other side of the roof
HiRes Image URL:[Click Me](#)

Job Number:LIN-25-701-TMP Album:Ricardo pics



File Name:Ricardo pics_0006.jpg
Description:Overview pics
HiRes Image URL:[Click Me](#)

Job Number:LIN-25-701-TMP Album:Ricardo pics



File Name:Ricardo pics_0007.jpg
Description:Overview pics
HiRes Image URL:[Click Me](#)

Job Number:LIN-25-701-TMP Album:Ricardo pics



File Name:Ricardo pics_0009.jpg
Description:Overview pics
HiRes Image URL:[Click Me](#)

Job Number:LIN-25-701-TMP Album:Ricardo pics



File Name:Ricardo pics_0017.jpg
Description:Overview pics
HiRes Image URL:[Click Me](#)

Job Number:LIN-25-701-TMP Album:Ricardo pics



File Name:Ricardo pics_0018.jpg
Description:Overview pics of damage roof
HiRes Image URL:[Click Me](#)

Job Number:LIN-25-701-TMP Album:Ricardo pics



File Name:Ricardo pics_0001.jpg
Description:Overview pics of roof
HiRes Image URL:[Click Me](#)

Job Number:LIN-25-701-TMP Album:Ricardo pics



File Name:Ricardo pics_0013.jpg
Description:Overview pics of roof tarp
HiRes Image URL:[Click Me](#)

Job Number:LIN-25-701-TMP Album:Ricardo pics



File Name:Ricardo pics_0003.jpg
Description:Overview pictures of roof
HiRes Image URL:[Click Me](#)

Job Number:LIN-25-701-TMP Album:Ricardo pics



File Name:Ricardo pics_0012.jpg
Description:Roof damage
HiRes Image URL:[Click Me](#)

Job Number:LIN-25-701-TMP Album:Ricardo pics



File Name:Ricardo pics_0014.jpg
Description:Roof damage
HiRes Image URL:[Click Me](#)

Job Number:LIN-25-701-TMP Album:Ricardo pics



File Name:Ricardo pics_0004.jpg
Description:Roof tarp
HiRes Image URL:[Click Me](#)

Job Number:LIN-25-701-TMP Album:Ricardo pics



File Name:Ricardo pics_0005.jpg

Description:Roof tarp

HiRes Image URL:[Click Me](#)

Job Number:LIN-25-701-TMP Album:Ricardo pics



File Name:Ricardo pics_0008.jpg

Description:Roof tarp

HiRes Image URL:[Click Me](#)

Job Number:LIN-25-701-TMP Album:Ricardo pics



File Name:Ricardo pics_0016.jpg

Description:Roof tarp

HiRes Image URL:[Click Me](#)

Job Number:LIN-25-701-TMP Album:Ricardo_pics



File Name:Ricardo pics_0010.jpg

Description:Roof tarp complete

HiRes Image URL:[Click Me](#)

Job Number:LIN-25-701-TMP Album:Ricardo_pics



File Name:Ricardo pics_0011.jpg
Description:Roof tarp. Complete
HiRes Image URL:[Click Me](#)



Lawton Construction & Restoration

PO Box 1966
Lincoln CA 95648
Tax id: 20-5680762

Client: 4076 WEYMOUTH LN
Property: 4076 WEYMOUTH LN
SACRAMENTO , CA 95823

Operator: TRAVI

Estimator: Travis Gabourie

Business: (530) 308-0728

Type of Estimate:

Date Entered: 10/2/2025

Date Assigned:

Price List: CASA8X_OCT25

Labor Efficiency: Restoration/Service/Remodel

Estimate: 4076_WEYMOUTH_LN_T-1

Emergency Roof Estimate



Lawton Construction & Restoration

PO Box 1966
Lincoln CA 95648
Tax id: 20-5680762

4076_WEYMOUTH_LN_T-1

4076_WEYMOUTH_LN_T-1

CAT	SEL	ACT DESCRIPTION		REMOVE	REPLACE	TAX	TOTAL
	CALC	QTY					
1. SCF	RNTHLD	+ Fall protection harness and lanyard (per day)					
	1	1.00 DA		0.00+	8.00 =	0.00	8.00
2. RFG	HIGH	+ Additional charge for high roof (2 stories or greater)					
	1.5	1.50 SQ		0.00+	41.31 =	0.00	61.97
3. TMP	TARPS	+ Tarp - poly - w/sandbags - per sq ft (lab & mat)					
	150	150.00 SF		0.00+	3.10 =	7.48	472.48
Total: 4076_WEYMOUTH_LN_T-1						7.48	542.45
Line Item Totals: 4076_WEYMOUTH_LN_T-1						7.48	542.45



Lawton Construction & Restoration

PO Box 1966
Lincoln CA 95648
Tax id: 20-5680762

Summary

Line Item Total	534.97
Material Sales Tax	7.48
Replacement Cost Value	\$542.45
Net Claim	\$542.45

Travis Gabourie



Lawton Construction & Restoration

PO Box 1966
Lincoln CA 95648
Tax id: 20-5680762

Recap of Taxes

	Material Sales Tax (8.75%)	Storage Rental Tax (8.75%)
Line Items	7.48	0.00
Total	7.48	0.00



Lawton Construction & Restoration

PO Box 1966
Lincoln CA 95648
Tax id: 20-5680762

Recap by Room

Estimate: 4076_WEYMOUTH_LN_T-1	534.97	100.00%
Subtotal of Areas	534.97	100.00%
Total	534.97	100.00%



Lawton Construction & Restoration

PO Box 1966
Lincoln CA 95648
Tax id: 20-5680762

Recap by Category

Items	Total	%
ROOFING	61.97	11.42%
SCAFFOLDING	8.00	1.47%
TEMPORARY REPAIRS	465.00	85.72%
Subtotal	534.97	98.62%
Material Sales Tax	7.48	1.38%
Total	542.45	100.00%



Loss Type:

Date Of Loss:

Loss Category:Residential

Customer Name:Wildwood Homeowner's Association

E-mail Address:

Job Address:4076 WEYMOUTH LN
SACRAMENTO, CA, 95823

Main Contact Number:1-916-392-3613

Billing Address:4088 Savannah Ln
Sacramento, CA, 95823

Job Number:LIN-25-702-TMP Album:Ricardo pics



File Name:Ricardo pics_0002.jpg

Description:Front elevation

HiRes Image URL:[Click Me](#)

Job Number:LIN-25-702-TMP Album:Ricardo pics



File Name:Ricardo pics_0004.jpg
Description:Front elevation
HiRes Image URL:[Click Me](#)

Job Number:LIN-25-702-TMP Album:Ricardo pics



File Name:Ricardo pics_0006.jpg
Description:Old roof tarp
HiRes Image URL:[Click Me](#)

Job Number:LIN-25-702-TMP Album:Ricardo pics



File Name:Ricardo pics_0008.jpg

Description:Old tarp

HiRes Image URL:[Click Me](#)

Job Number:LIN-25-702-TMP Album:Ricardo pics



File Name:Ricardo pics_0009.jpg

Description:Old tarp

HiRes Image URL:[Click Me](#)

Job Number:LIN-25-702-TMP Album:Ricardo pics



File Name:Ricardo pics_0007.jpg

Description:Overview pics

HiRes Image URL:[Click Me](#)

Job Number:LIN-25-702-TMP Album:Ricardo pics



File Name:Ricardo pics_0001.jpg

Description:Roof tarp

HiRes Image URL:[Click Me](#)

Job Number:LIN-25-702-TMP Album:Ricardo pics



File Name:Ricardo pics_0003.jpg
Description:Roof tarp
HiRes Image URL:[Click Me](#)

Job Number:LIN-25-702-TMP Album:Ricardo pics



File Name:Ricardo pics_0011.jpg
Description:Roof tarp
HiRes Image URL:[Click Me](#)

Job Number:LIN-25-702-TMP Album:Ricardo pics



File Name:Ricardo pics_0012.jpg
Description:Roof tarp
HiRes Image URL:[Click Me](#)

Job Number:LIN-25-702-TMP Album:Ricardo pics



File Name:Ricardo pics_0013.jpg
Description:Roof tarp
HiRes Image URL:[Click Me](#)



Lawton Construction & Restoration

PO Box 1966
Lincoln CA 95648
Tax id: 20-5680762

Client: 4149 Brookfield Dr
Property: 4149 Brookfield Dr
SACRAMENTO , CA 95823

Operator: TRAVI

Estimator: Travis Gabourie

Business: (530) 308-0728

Type of Estimate:

Date Entered: 10/2/2025

Date Assigned:

Price List: CASA8X_OCT25

Labor Efficiency: Restoration/Service/Remodel

Estimate: 4149_BROOKFIELD_TMP

Emergency Roof Estimate



Lawton Construction & Restoration

PO Box 1966
Lincoln CA 95648
Tax id: 20-5680762

4149_BROOKFIELD_TMP

4149_BROOKFIELD_TMP

CAT	SEL	ACT DESCRIPTION		REMOVE	REPLACE	TAX	TOTAL
	CALC	QTY					
1. SCF	RNTHLD	+ Fall protection harness and lanyard (per day)					
	1	1.00 DA		0.00+	8.00 =	0.00	8.00
2. RFG	HIGH	+ Additional charge for high roof (2 stories or greater)					
	3	3.00 SQ		0.00+	41.31 =	0.00	123.93
3. TMP	TARPS	+ Tarp - poly - w/sandbags - per sq ft (lab & mat)					
	300	300.00 SF		0.00+	3.10 =	14.96	944.96
Total: 4149_BROOKFIELD_TMP						14.96	1,076.89
Line Item Totals: 4149_BROOKFIELD_TMP						14.96	1,076.89



Lawton Construction & Restoration

PO Box 1966
Lincoln CA 95648
Tax id: 20-5680762

Summary

Line Item Total	1,061.93
Material Sales Tax	14.96
Replacement Cost Value	\$1,076.89
Net Claim	\$1,076.89

Travis Gabourie



Lawton Construction & Restoration

PO Box 1966
Lincoln CA 95648
Tax id: 20-5680762

Recap of Taxes

	Material Sales Tax (8.75%)	Storage Rental Tax (8.75%)
Line Items	14.96	0.00
Total	14.96	0.00



Lawton Construction & Restoration

PO Box 1966
Lincoln CA 95648
Tax id: 20-5680762

Recap by Room

Estimate: 4149_BROOKFIELD_TMP	1,061.93	100.00%
Subtotal of Areas	1,061.93	100.00%
Total	1,061.93	100.00%



Lawton Construction & Restoration

PO Box 1966
Lincoln CA 95648
Tax id: 20-5680762

Recap by Category

Items	Total	%
ROOFING	123.93	11.51%
SCAFFOLDING	8.00	0.74%
TEMPORARY REPAIRS	930.00	86.36%
Subtotal	1,061.93	98.61%
Material Sales Tax	14.96	1.39%
Total	1,076.89	100.00%



Loss Type:

Date Of Loss:

Loss Category:Residential

Customer Name:Wildwood Homeowner's Association

E-mail Address:

Job Address:4149 BROOKFIELD DR
SACRAMENTO, CA, 95823

Main Contact Number:1-916-392-3613

Billing Address:4088 Savannah Ln
Sacramento, CA, 95823

Job Number:LIN-25-703-TMP Album:4149 tarp



File Name:4149 tarp_0004.jpg
Description:10-01-25. Other crew
HiRes Image URL:[Click Me](#)

Job Number:LIN-25-703-TMP Album:4149 tarp



File Name:4149 tarp_0003.jpg
Description:10-01-25. Unit 4149 Make new tarp
HiRes Image URL:[Click Me](#)

Job Number:LIN-25-703-TMP Album:4149 tarp



File Name:4149 tarp_0006.jpg
Description:10-01-25. Unit 4149 New tarp
HiRes Image URL:[Click Me](#)

Job Number:LIN-25-703-TMP Album:4149 tarp



File Name:4149 tarp_0007.jpg
Description:10-01-25. Unit 4149 Overview
HiRes Image URL:[Click Me](#)

Job Number:LIN-25-703-TMP Album:4149 tarp



File Name:4149 tarp_0008.jpg
Description:10-01-25. Unit 4149 Overview
HiRes Image URL:[Click Me](#)

Job Number:LIN-25-703-TMP Album:4149 tarp



File Name:4149 tarp_0009.jpg
Description:10-01-25. Unit 4149 Overview
HiRes Image URL:[Click Me](#)

Job Number:LIN-25-703-TMP Album:4149 tarp



File Name:4149 tarp_0010.jpg
Description:10-01-25. Unit 4149 Overview
HiRes Image URL:[Click Me](#)

Job Number:LIN-25-703-TMP Album:4149 tarp



File Name:4149 tarp_0001.jpg

Description:10-01-25. Unit 4149 Remove old tarp

HiRes Image URL:[Click Me](#)

Job Number:LIN-25-703-TMP Album:4149 tarp



File Name:4149 tarp_0002.jpg

Description:10-01-25. Unit 4149 Remove old tarp

HiRes Image URL:[Click Me](#)

Job Number:LIN-25-703-TMP Album:4149 tarp



File Name:4149 tarp_0005.jpg
Description:10-01-25. Unit 4149 Tarp roof
HiRes Image URL:[Click Me](#)



Lawton Construction & Restoration

PO Box 1966
Lincoln CA 95648
Tax id: 20-5680762

Client: 4075 Savannah Ln
Property: 4075 Savannah Ln
SACRAMENTO , CA 95823

Operator: TRAVI

Estimator: Travis Gabourie

Business: (530) 308-0728

Type of Estimate:

Date Entered: 10/2/2025

Date Assigned:

Price List: CASA8X_OCT25

Labor Efficiency: Restoration/Service/Remodel

Estimate: 4075_SAVANNAH_TMP

Emergency Roof Estimate



Lawton Construction & Restoration

PO Box 1966
Lincoln CA 95648
Tax id: 20-5680762

4075_SAVANNAH_TMP

4075_SAVANNAH_TMP

CAT	SEL	ACT DESCRIPTION					
	CALC	QTY	REMOVE	REPLACE	TAX	TOTAL	
1. SCF	RNTHLD	+ Fall protection harness and lanyard (per day)					
	1	1.00 DA	0.00+	8.00 =	0.00	8.00	
2. RFG	HIGH	+ Additional charge for high roof (2 stories or greater)					
	4	4.00 SQ	0.00+	41.31 =	0.00	165.24	
3. TMP	TARPS	+ Tarp - poly - w/sandbags - per sq ft (lab & mat)					
	400	400.00 SF	0.00+	3.10 =	19.95	1,259.95	
Total: 4075_SAVANNAH_TMP					19.95	1,433.19	
Line Item Totals: 4075_SAVANNAH_TMP					19.95	1,433.19	



Lawton Construction & Restoration

PO Box 1966
Lincoln CA 95648
Tax id: 20-5680762

Summary

Line Item Total	1,413.24
Material Sales Tax	19.95
Replacement Cost Value	\$1,433.19
Net Claim	\$1,433.19

Travis Gabourie



Lawton Construction & Restoration

PO Box 1966
Lincoln CA 95648
Tax id: 20-5680762

Recap of Taxes

	Material Sales Tax (8.75%)	Storage Rental Tax (8.75%)
Line Items	19.95	0.00
Total	19.95	0.00



Lawton Construction & Restoration

PO Box 1966
Lincoln CA 95648
Tax id: 20-5680762

Recap by Room

Estimate: 4075_SAVANNAH_TMP	1,413.24	100.00%
Subtotal of Areas	1,413.24	100.00%
Total	1,413.24	100.00%



Lawton Construction & Restoration

PO Box 1966
Lincoln CA 95648
Tax id: 20-5680762

Recap by Category

Items	Total	%
ROOFING	165.24	11.53%
SCAFFOLDING	8.00	0.56%
TEMPORARY REPAIRS	1,240.00	86.52%
Subtotal	1,413.24	98.61%
Material Sales Tax	19.95	1.39%
Total	1,433.19	100.00%



Loss Type:

Date Of Loss:

Loss Category:Residential

Customer Name:Wildwood Homeowner's Association

E-mail Address:

Job Address:4075 SAVANNAH LN
SACRAMENTO, CA, 95823

Main Contact Number:1-916-392-3613

Billing Address:4088 Savannah Ln
Sacramento, CA, 95823

Job Number:LIN-25-704-TMP Album:Roof tarp



File Name:Roof tarp_0009.jpg

Description:10-01-25 front gutter was damaged

HiRes Image URL:[Click Me](#)

Job Number:LIN-25-704-TMP Album:Roof tarp




File Name:Roof tarp_0007.jpg

Description:10-01-25 roof tarp overview

HiRes Image URL:[Click Me](#)

Job Number:LIN-25-704-TMP Album:Roof tarp



File Name:Roof tarp_0011.jpg

Description:10-01-25 roof overview


HiRes Image URL:[Click Me](#)

Job Number:LIN-25-704-TMP Album:Roof tarp



File Name:Roof tarp_0012.jpg
Description:10-01-25 roof overview
HiRes Image URL:[Click Me](#)

Job Number:LIN-25-704-TMP Album:Roof tarp



File Name:Roof tarp_0015.jpg
Description:10-01-25 roof overview
HiRes Image URL:[Click Me](#)

Job Number:LIN-25-704-TMP Album:Roof tarp



File Name:Roof tarp_0016.jpg
Description:10-01-25 roof overview
HiRes Image URL:[Click Me](#)

Job Number:LIN-25-704-TMP Album:Roof tarp



File Name:Roof tarp_0018.jpg
Description:10-01-25 roof overview
HiRes Image URL:[Click Me](#)

Job Number:LIN-25-704-TMP Album:Roof tarp



File Name:Roof tarp_0001.jpg
Description:10-01-25 roof tarp
HiRes Image URL:[Click Me](#)

Job Number:LIN-25-704-TMP Album:Roof tarp



File Name:Roof tarp_0002.jpg
Description:10-01-25 roof tarp
HiRes Image URL:[Click Me](#)

Job Number:LIN-25-704-TMP Album:Roof tarp



File Name:Roof tarp_0004.jpg
Description:10-01-25 roof tarp
HiRes Image URL:[Click Me](#)

Job Number:LIN-25-704-TMP Album:Roof tarp



File Name:Roof tarp_0005.jpg
Description:10-01-25 roof tarp
HiRes Image URL:[Click Me](#)

Job Number:LIN-25-704-TMP Album:Roof tarp



File Name:Roof tarp_0021.jpg
Description:10-01-25 roof tarp
HiRes Image URL:[Click Me](#)

Job Number:LIN-25-704-TMP Album:Roof tarp



File Name:Roof tarp_0022.jpg
Description:10-01-25 roof tarp
HiRes Image URL:[Click Me](#)

Job Number:LIN-25-704-TMP Album:Roof tarp



File Name:Roof tarp_0003.jpg

Description:10-01-25 roof tarp overview

HiRes Image URL:[Click Me](#)

Job Number:LIN-25-704-TMP Album:Roof tarp



File Name:Roof tarp_0006.jpg

Description:10-01-25 roof tarp overview

HiRes Image URL:[Click Me](#)

Job Number:LIN-25-704-TMP Album:Roof tarp



File Name:Roof tarp_0008.jpg

Description:10-01-25 roof tarp overview

HiRes Image URL:[Click Me](#)

Job Number:LIN-25-704-TMP Album:Roof tarp



File Name:Roof tarp_0010.jpg

Description:10-01-25 roof tarp overview

HiRes Image URL:[Click Me](#)

Job Number:LIN-25-704-TMP Album:Roof tarp



File Name:Roof tarp_0013.jpg
Description:10-01-25 tarping roof
HiRes Image URL:[Click Me](#)

Job Number:LIN-25-704-TMP Album:Roof tarp



File Name:Roof tarp_0014.jpg
Description:10-01-25 tarping roof
HiRes Image URL:[Click Me](#)

Job Number:LIN-25-704-TMP Album:Roof tarp



File Name:Roof tarp_0020.jpg
Description:10-01-25 tarping roof
HiRes Image URL:[Click Me](#)

Job Number:LIN-25-704-TMP Album:Roof tarp



File Name:Roof tarp_0017.jpg
Description:10-01-25 tarping roof
HiRes Image URL:[Click Me](#)

Job Number:LIN-25-704-TMP Album:Roof tarp



File Name:Roof tarp_0019.jpg
Description:10-01-25 tarping roof
HiRes Image URL:[Click Me](#)