



## **Board of Directors**

Jeff Gates President Jackie Rose Vice President Lisa Lindsay Secretary Steve Snead Treasurer Linda DeAngelo Member-at-Large

## Management Company

Reliable Assoc Management (916) 564-2115 FAX (916) 564-2118 1600 Sac Inn Drive Sacramento, CA


## Wildwood Offfice

Lisa Lindsay Contract Mgr. (916) 821-7796 FAX (916) 392-3640

> Attorney Carter Glahn (916) 929-8383

## NEXT MEETING

Thursday, January 18, 2007 6:00 p.m. 4088 Savannah Lane Sacramento, CA 95823



# Did you know?


In 1999 to 2001, the units received new roofs and new paint. The Board in place at that time approved the expenditure of these repairs in good faith.

The contractor for the roof used substandard materials on all 137 units and the contractor hired to paint failed to replace dry-rot with new t-1-11 wood siding and on many units, painted over the existing dry-rot.

At the same time, the Association had only a part time Manager to oversee this major project.

There was no inspection done on the siding and paint projects, nor was payments withheld from the contractors who performed the unacceptable work.

# New Approach



In 2003, the Manager realized the new roofs were a problem. An immediate patch job was done on those roofs that had obvious degradation...but it was just that a patch job. The Manager also took the initiative to pursue the contractor who installed the faulty roofs.

The roofing contractor retired to Mexico and his insurance company did not cooperate.

Wildwood applauds the Managers efforts....but the cost of legally pursuing the shady contractor was prohibitive when the money was needed to repair roofs again.

# Further Discovery

Due to the severity of the dry rot problem on the south sides of several buildings, water intrusion was so severe in a few units that moisture ran down the interior walls.



## SOME OF THE 2006 EXPENDITURES TO DATE

ROOF PATCHING – 137 UNITS = APPROX **55,000** 

SHED ROOFS = 120 UNITS

APPROX **60,000** 

REPAIR AND BLACK TOP ALL STREETS CARPORTS, AND DRIVEWAYS PAVEMENT = APPROX **30,000** 

T-1-11 WOOD TO REPAIR ALL 137 UNITS = APRROX **40,000** 

PRIMER AND PAINT FOR 137 UNITS (23 BLDGS) = APPROX **17,000** 

SECURITY LIGHT ADDITION – 14 BLDGS = APPROX **6,000** 

GUTTER CLEANING/REPAIR FOR 137 GUTTERS = APPROX **2,500** 

COST OF LABOR TO DATE FOR CONSTRUCTION = APPROX **30,000** 

> Total: **\$237,500.00**

# Where we Are Today

# ROOFS

All 137 roofs have been repaired per the following:

- > Missing or damaged shingles have been replaced
- > All loose shingles were nailed back down
- > Ridges were reinstalled properly
- > Flashing was nailed down
- > Step flashing was repaired and jacks were nailed down
- > Damaged dormers were replaced
- > All flashing, jacks and dormers were painted

# WATER HEATER SHED ROOFS

Since July of 2006 approximately 120 water heater shed roofs have been re-engineered to a very moderate pitch to allow rain water to sheet off the roof...not to sit. The design was prototyped to accommodate the funds available for the shed roof expenditure. The poor construction of the water heater shed roofs was an additional cause of water intrusion and dry rot. The shed roofs were flat and therefore over the years the weight of rain water has caused a "bowl" effect in the roofs.


# T-1-11 SIDING AND PAINT

The most severely damaged buildings have been reconstructed 1<sup>st</sup>. These addresses are: 4183 to 4197 Brookfield 4087 to 4097 Weymouth (in progress approx 60% complete) 4079 to 4085 Weymouth (approx 90% complete) 4074 to 4084 Weymouth (approx 90% complete) 4086 to 4100 Weymouth (approx 60% complete)

The plan is to complete a building per month starting after rainy season...hopefully around March 2007.



# Worried about Reserves?



#### Civil Code 1350 Title

This title shall be known and may be cited as the Davis-Stirling Common Interest Development Act.

#### Civil Code 1352 Creation of Common Interest Development and Applicability of this Act

This title applies and a common interest development is created whenever a separate interest coupled with an interest in the common area or membership in the association is, or has been, conveyed, provided, all of the following are recorded:

(a) A declaration. (b) A condominium plan, if any exists.

(c) A final map or parcel map, if Division 2 (commencing with Section 66410) of Title 7 of the Government Code requires the recording of either a final map or parcel map for the common interest development.

## **HIERARCHY OF DOCUMENTS**

Common interest developments have a number of documents controlling the development. Not all documents are created equal--some have more authority than others. The hierarchy of authority among documents is as follows:

Davis – Stirling Act then:

- 1. Recorded map or condominium plan
- 2. Declaration of Covenants, Conditions and Restrictions (CC&Rs)
- 3. Articles of Incorporation
- 4. Bylaws
- 5. Rules and Regulations

Conflicts between documents can often be resolved by referring to the hierarchy of authority. However, statutes and case law may also control particular issues. Boards should seek a legal opinion whenever they discover a conflict.

Updated 11/16/2006

