



MicroTest Laboratories Inc. AIHA EMPAT# 160934
3110 Gold Canal Dr. Ste. A. Rancho Cordova, CA 95670
PH 916.567.9808 | FX 916.404.0302
www.microtestlabsinc.com | service@microtestlabsinc.com

Project ID
MT012333163

CLIENT INFORMATION

Company Name Golden State Inspections, Inc.
Address 9921 Horn Road, Ste. B
Sacramento, CA 95827
Phone (916) 836 - 8337
Email info@goldenstateservices.net

SAMPLE

Date Monday, June 12, 2023
Time 3:25 PM

MicroTest
Laboratories

Analytical Data

JOB SITE INFORMATION

Sampler Jason B
Project
Address 4085 Weymouth Lane
Sacramento, CA 95823

Non-Viable Bioaerosol Analysis

Accession No. / Sample ID	33163-1 / 5398700			33163-2 / 5398687					
Sample Location	Outside Air Back Porch			Inside Air Kitchen Counter					
Spore Types:	Raw Count	Count/m ³	% of Area	Raw Count	Count/m ³	% of Area	Raw Count	Count/m ³	% of Area
Alternaria				3	40	0.763			
Ascospores	129	1720	43.144	200	2666	50.891			
Aspergillus/Penicillium	21	280	7.023	66	880	16.794			
Basidiomycetes	27	360	9.03	27	360	6.87			
Cercospora									
Chaetomium									
Cladosporium	113	1506	37.793	87	1160	22.137			
Curvularia									
Drechslera/Bipolaris				2	27	0.509			
Epicoccum				1	13	0.254			
Fusarium									
Nigrospora									
Oidium/Peronospora	2	27	0.669						
Other Hyaline									
Pithomyces									
Scopulariopsis									
Smuts/Rusts/Periconia/Myxomycetes	4	53	1.338	4	53	1.018			
Stachybotrys									
Stemphylium	1	13	0.334						
Torula				3	40	0.763			
Ulocladium	2	27	0.669						
Total Fungi	299	3986	100%	393	5239	100%			
Background	3			3					
Fibrous Particulate	3			3					
Hyphal Fragments	1			2					
Pollen	19			28					
Skin Fragments	1			3					

Date Received: Monday, June 12, 2023
Date Analyzed: Tuesday, June 13, 2023
Date Reported: Tuesday, June 13, 2023

Samples Received: 2
Samples Analyzed: 2

Analyst: May Yang

Authorized Signatory:

Kelly Favero - Lab Manager



MicroTest Laboratories Inc. AIHA EMPAT# 160934
3110 Gold Canal Dr. Ste. A. Rancho Cordova, CA 95670
PH 916.567.9808 | FX 916.404.0302
www.microtestlabsinc.com | service@microtestlabsinc.com

Project ID
MT012333164

CLIENT INFORMATION

Company Name Golden State Inspections, Inc.
Address 9921 Horn Road, Ste. B
Sacramento, CA 95827
Phone (916) 836 - 8337
Email info@goldenstateservices.net

SAMPLE

Date Monday, June 12, 2023
Time 3:25 PM

**MicroTest
Laboratories**

Analytical Data

JOB SITE INFORMATION

Sampler Jason B
Project
Address 4085 Weymouth Lane
Sacramento, CA 95823

Analysis of Fungal Spores, Structures, Hyphae and Other Particulates from Bulk or Tape Samples by Optical Microscopy

Accession Number	Amorphous Debris/Description	Pollen / Miscellaneous	Molds Observed: Mycelia or Sporulating Structures	Comments
33164-1 Air Return	3+ Amorphous Debris 2+ Particulate Debris	3+ Fibrous Particulate Rare Hyphal Fragments 3+ Skin Fragments Rare Pollen	Rare Ascomyetes Rare Aspergillus/Penicillium Rare Basidiomycetes Rare Cladosporium Rare Smuts/Rusts/Periconia/Myxomycetes	

Note: Quantities of molds seen are graded from Rare to 4+, with 4+ denoting the highest numbers observed on microscopic examination. "Rare" indicates presence, but in very low numbers.

Following are **general** comments regarding the molds detected from the samples collected and submitted

Date Received: Monday, June 12, 2023
Date Analyzed: Tuesday, June 13, 2023
Date Reported: Tuesday, June 13, 2023

Samples Received: 1
Samples Analyzed: 1

Analyst: May Yang

Authorized Signatory:

Kelly Favero - Lab Manager

MicroTest Laboratories, Inc. does not associate these analyses with any event or significance other than that the organisms were present in the submitted samples. The interpretation of this report should not rule out the presence or absence of other organisms.

for office use only

Accession Numbers

33163-64

CLIENT INFORMATION

Company Golden State Inspections, Inc.

Name

Address 9921 Horn Road Ste. B

Sacramento, CA 95827

Phone (916) 836-8337

Email info@goldenstateservices.net

SAMPLE

Date 6/12/23

Time 3:25 p.m.

MicroTest Laboratories

Chain-Of-Custody

JOB SITE INFORMATION

Sampler Jason B

Project

Site

Address 4085 Weymouth Ln
Sacramento CA 95823

Job #

PO #

TURN AROUND	ASBESTOS	LEAD	MICROBIOLOGICAL		FIRE RESIDUE
Rush (3 Hour)	PLM*	Paint Chip	☒ Spore Trap	☐ Sewage Screen	☐ Spore Trap
Same Day (6 Hour)	TTFP*	Wipe	☐ DP-Tape	☐ HPC*	☐ DP-Tape
☒ 24 Hour	400 Pt. Ct.	Air	☒ DP-Swab	☐ HPC* with ID	☐ Wipes
2-Day	1000 Pt. Ct.	Soil	☐ DP-Bulk	☐ Other	
3-Day	PCM*	TTLc*/STLC*	☐ Andersen		☐ Semi-Quantitative
7-Day	TEM*	TCLP*			☐ Quantitative

[illegible]

Special Instructions:

Relinquished by (Client)	Date/Time
	6/12/23 4:22 PM

Relinquished by (Lab)	Date/Time

Received By (Lab)	Date/Time
<i>[Signature]</i>	6/12/23 4:24 PM

Received By (Client)	Date/Time

Total Number of Samples 3
COC Page # 1 of 1

PLM* Polarized Light Microscopy | TTFP* Test Till First Positive | PCM* Phase Contrast Microscopy | TEM* Transmission Electron Microscopy | TTL* Total Threshold Limit Concentration | STLC* Soluble Threshold Limit Concentration | TCLP* Toxicity Characteristic Leaching Procedure | HPC* Heterotrophic Plate Count